


OWS BETA SETUP

QUICK START GUIDE


Enable Beta Software Installation

1. Log in to **OpenEye Web Services (OWS)** at <https://ows.openeye.net/login>.

2. In the **Customer Accounts** list, click **MANAGE** next to the account that you want to enable Beta for.




3. Click **Software Update Options** and check the box for **Allow Company to install Beta Software**, then click **Save**.



4. Now go back to the **Customer Accounts** list and click **SELECT** next to the account Beta was enabled for.


5. On the **Recorder Management** menu select **Recorder Groups**.





6. **Add New Recorder Group** or Edit an existing one by clicking **VIEW**.



7. Click **Software Update Options** and enable **Allow Recorders to Install Beta Software**, then click **Save**.



8. Click **Recorders** and add recorders permitted to receive Beta software.



9. The recorders added to the **Recorder Group** now have the ability to install Beta software when one is available. Every 6 hours (or after a reboot) the recorder will check for software updates. A notice will show up on the recorder when the update is ready to install.

